

**Niagara Falls Boulevard  
Niagara County, New York  
2020 Removal Action Daily Report**

**Date:** Wednesday, January 15, 2020

**Personnel On-Site:**

EPA OSC – Peter Lisichenko

START V – Sean Quinn, & Tom O'Donnell

ERRS Contractor: Guardian Environmental Services (GES)

**Weather:** Partly cloudy, 10% chance of rain, Lo: 31°F, High: 39°F, Winds: 5 to 10 mph, due SW, 77% humidity.

**Health and Safety:** Safety topics included: being aware of slips, trips, and falls, site traffic and heavy equipment awareness, cold stress, using proper personal protective equipment (PPE), high winds, and radiation hazards.

**Activities Completed:**

1. ERRS completed laying concrete in WH3.
2. START V continued to process samples in HPGe.
3. ERRS resumed excavations on A12, on the North side of the soil pile.
4. START V resumed scanning excavations in A12 to ensure SSAL were met.
5. START V collected a total of 2 post excavation soil samples in A12.
6. ERRS began site shutdown procedures.
7. At the end of the work day, START V uploaded field data to the EPA internet SharePoint site designated for the Site.

**Planned Activities for January 16, 2020:**

1. START V will continue to process samples in HPGe.
2. ERRS will continue site shutdown operations.

**Niagara Falls Boulevard  
Niagara County, New York  
2020 Removal Action Daily Report**

**Soil Excavation & Backfill Data:**

Soil Volume Excavated Today (In Cubic Yards)	<b>246.66</b>
Cumulative Soil Volume Excavated (In Cubic Yards) <sup>1</sup>	<b>3,739.16</b>
Total Number of Disposal Trucks Today	<b>19</b>
Total Number of Disposal Trucks to Date	<b>359</b>
Soil Volume Transferred to Disposal Trucks	<b>437</b>
Cumulative Disposal Volume Removed To Date ( In Tons)	<b>8,234</b>
Number of Backfill Trucks Today	<b>0</b>
Number of Backfill Trucks to Date	<b>243</b>
Backfill Received Today (In Tons)	<b>604.71</b>
Cumulative Backfill Volume to Date (In Tons)	<b>8737.72</b>

<sup>1</sup> Corrected value based on ERRS reported totals for each area.

**Niagara Falls Boulevard  
Niagara County, New York  
2020 Removal Action Daily Report**

**Site Photographs**



View of ERRS conducting excavations on the north side of the soil pile in A12.



View of ERRS conducting backfilling in A11 on the west side of the soil pile.

**Niagara Falls Boulevard  
Niagara County, New York  
2020 Removal Action Daily Report**